


Internal view of Harting connector 72 pins from inside the LV box



Comment

For simple orientation among power supplies:
 Positive polarity of each power supply is on the left side.
 Negative polarity of each power supply is on the right side.
Dangerous: Be careful, the orientation of negative power supply pins on Harting connector has been changed due to a special request of some project collaborators!

| | | | | |
|--------------|------------|------------|------------|------------|
| Rev. | 24.09.2003 | 23.11.2003 | 31.01.2004 | 12.07.2004 |
| Zdenek Kotek | 22.10.2003 | 26.11.2003 | 16.02.2004 | 13.07.2004 |
| | 06.11.2003 | 15.12.2003 | 10.03.2004 | 16.07.2004 |
| | 08.11.2003 | 08.01.2004 | 16.03.2004 | 23.02.2005 |